
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Yes

No

N/A

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001261 Address: 333 Burma Road **Date Inspected:** 16-Jan-2008

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No

Delayed / Cancelled: 34-0006 **Bridge No: Component:** N/A

Summary of Items Observed:

On this date, the Caltrans Quality Assurance (QA) representative, John P. Tracy, conducted assessments while on site at Zhenhua Port Machinery Company (ZPMC) for Caltrans Project 04-0120F4-SAS. The following is the detailed review of the following observations:

On this reporting day, the Caltrans representative did not observe any project related functions because the ferry to the island facility was canceled due to heavy fog.

Summary of Conversations:

No significant conversation took place for this reporting date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By: Tracy, John Quality Assurance Inspector **Reviewed By:** Cuellar.Robert **QA** Reviewer